

# ACCESSORIES

Step 1

CHOOSE  
YOUR TOOL



Step 2

APPLY THIS  
ATTACHMENT



Adhesive  
Attachment  
5402A10

Step 3

SECURE  
ATTACHMENT



Choke-on Wire Loop  
5317A10

COMPLETE  
SOLUTION



Tape Measure  
Holder  
5402A10



Battery Boot  
5401A1



OBJECTS UP TO 2LB